DOE/ID-10880 Revision 0 August 2001



OU 3-14 Remedial Investigation/Feasibility Study Additional Soil Sites Summary Report



OU 3-14 Remedial Investigation/Feasibility Study Additional Soil Sites Summary Report

Published August 2001

Prepared for the U.S. Department of Energy Idaho Operations Office

ABSTRACT

The Waste Area Group (WAG) 3 soil Sites CPP-61 (polychlorinated biphenyl spill in CPP-718 Transformer Yard), CPP-81 (abandoned CPP-637/CPP-620 vessel off-gas line), and CPP-82 (abandoned 1.5-in. line, PLA-776 West of Beech Street) were investigated as part of the Idaho Nuclear Technology and Engineering Center WAG 3 remedial investigation/feasibility study process. The Operable Unit (OU) 3-13 Final Record of Decision assigned the three soil Sites, CPP-61, CPP-81, and CPP-82, to OU 3-14 for disposition.

This OU 3-14 Remedial Investigation/Feasibility Study Additional Soil Sites Summary Report presents the archived information and regulatory actions that have been taken with regard to the soil Sites CPP-61, CPP-81, and CPP-82. Evaluation of this information supports previous determinations of "No Further Action" for CPP-61, CPP-81, and CPP-82.

CONTENTS

ABS	TRAC'	Т		iii		
ACR	ONYM	1S		ix		
1.	INTRODUCTION					
2.	CONTAMINATION SITE CPP-61					
	2.1	Summary				
	2.2	Release	e	2-1		
	2.3	Spill S	ite Description	2-1		
	2.4	Spill Response				
	2.5	Documentation History				
	2.6	Subsequent CPP-61 Site Activities				
	2.7					
		2.7.1 2.7.2	Nature and Extent of Remaining Contamination PCB Risk	2-12 2-12		
3.	CON	3-1				
	3.1	Summa	3-1			
	3.2	Incident				
	3.3	CERCLA Time-Critical Removal Action				
	3.4	Documentation History				
	3.5	Site Evaluation				
		3.5.1 3.5.2	Nature and Extent of Remaining Contamination Contaminant Risk	3-2 3-6		
4.	CONTAMINATION SITE CPP-82					
	4.1	Summary				
	4.2	Incident at Location A				
	4.3	Incident at Location B				
	4.4	Incident at Location C				

	4.5	Docum	ent History	4-9
	4.6	Site Ev	raluation	4-9
		4.6.1 4.6.2	Nature and Extent of Remaining Contamination	
5.	REC	OMMEN	NDED ACTION	5-1
	5.1	Site CF	PP-61	5-1
	5.2	Site CF	PP-81	5-1
	5.3	Site CF	PP-82	5-1
6.	REFI	ERENCE	ES	6-1
Appe	endix A	.—Supp	orting Documents	
Appe	endix B	—Photo	s of the Concrete Forms for XFR-8T2-4	
Appe	endix C	:—Daily	Construction Log Excerpts	
Appe	endix D	—Calcu	lation of Volume and Weight of Calcine Dissolved from VOG Line	
Appe	endix E	—WAG	3 OU 3-14 White Paper Evaluation of Sites CPP-61, CPP-81, and CPP-82	
			FIGURES	
1-1.			nlly controlled areas CPP-61, CPP-81, and CPP-82 within INTEC	1-2
2-1.	-		C showing CPP-718 and soil Sites CPP-61, CPP-81, and CPP-82 lan).	2-2
2-2.			CPP-61, sample locations, and analytical results prior to cleanup 2a)	2-3
2-3.	Origi	nal trans	former pad XRF-8T2-2, removed in July 1985	2-7
2-4.	Locat	ion of X	FR-8T2-2 and grounding grid with respect to CPP-718 and CPP-613	2-9
2-5.	Image	e of the 2	XFR-8T2-4 pad at Site CPP-61 looking northwest	2-11
3-1.			CPP-81 location; 3-in. VOG line located 2-3 ft below CPP-620 under an asphalt pad	3-1
4-1.	Schei	natic sho	owing Locations A, B-1, B-2, and B-3 of Site CPP-82	4-2
4-2.	Scher	natic sho	owing Location C of Site CPP-82	4-3
4-3.	Schen	natic fro	m Track 1 (WINCO 1992b) showing Location (Site) A	4-4

4-4.	Schematic from WINCO (1992b) showing Location (Site) B	4-6
4-5.	Schematic from WINCO (1992b) showing Location (Site) C	4-8
	TABLES	
2-1.	Soil sample numbers and grid location from the northwest corner of Building CPP-613	2-4
2-2.	Detected PCB contamination (ppm) prior to cleanup	2-5
2-3.	Transformer pad sample location and PCB concentration prior to cleanup	2-6
2-4.	PCB (Aroclor 1254) concentrations (mg/kg [ppm]) for residential soilcancer risk and HQ = 1 (adapted from EPA 2000)	2-12
3-1.	Sample calcine composition	3-3
3-2.	Species concentrations for the first series of acid and water flushes	3-4
3-3.	Species concentrations for the second series of acid and water flushes	3-5
3-4.	The contaminant concentrations [mg/kg (ppm)] for residential soil—10 ⁻⁶ cancer risk and HQ = 1 (adapted from EPA 2000)	3-8
3-5.	The contaminant concentrations (mg/kg [ppm]) for industrial soil—10 ⁻⁶ cancer risk and HQ = 1 (adapted from EPA 2000)	3-9
4-1.	Summary tables of risk-based soil screening concentrations	4-10
4-2.	The contaminant concentrations [mg/kg (ppm)] for residential soil—10 ⁻⁶ cancer risk and HQ = 1 (adapted from EPA 2000)	4-15
4-3.	The contaminant concentrations [mg/kg (ppm)] for industrial soil—10 ⁻⁶ cancer risk and HQ = 1 (adapted from EPA 2000)	4-16

ACRONYMS

bgs below ground surface

BRA baseline risk assessment

cpm counts per minute

DOE-ID Department of Energy Idaho Operations Office

EPA Environmental Protection Agency

FAST Fluorinel Dissolution Process and Fuel Storage

FDP fuel dissolution process

FS feasibility study

HP health physics

HQ hazard quotient

HWD hazardous waste determination

ICPP Idaho Chemical Processing Plant

IDEQ Idaho Department of Environmental Quality

IDW investigation-derived waste

INTEC Idaho Nuclear Technology and Engineering Center

N&IS nuclear and industrial safety

NFA no further action

OU operable unit

PCB polychlorinated biphenyl

PEW process equipment waste

PRG preliminary remediation goal

RCRA Resource Conservation and Recovery Act

RI remedial investigation

ROD Record of Decision

RWMC Radioactive Waste Management Complex

SAIC Science Applications International Corporation

TCE trichloroethylene

TSCA Toxic Substances Control Act

UREP Utilities Replacement Expansion Project

VOG vessel off-gas

WAG waste area group

OU 3-14 Remedial Investigation/Feasibility Study Additional Soil Sites Summary Report

1. INTRODUCTION

The Waste Area Group (WAG) 3 soil Sites CPP-61 (polychlorinated biphenyl [PCB] spill in CPP-718 Transformer Yard), CPP-81 (abandoned CPP-637/CPP-620 vessel off-gas [VOG] line), and CPP-82 (abandoned 1.5-in. line, PLA-776 west of Beech Street) were investigated as part of the Idaho Nuclear Technology and Engineering Center (INTEC) WAG 3 remedial investigation/feasibility study (RI/FS) process (see Figure 1-1). The Operable Unit (OU) 3-13 Final Record of Decision (ROD) (DOE-ID 1999) assigned three soil Sites, CPP-61, CPP-81, and CPP-82, to OU 3-14 for disposition.

The OU 3-14 Work Plan (DOE-ID 2000) calls for a summary report on the soil Sites CPP-61, CPP-81, and CPP-82 to evaluate each site with regard to their Track 1 decision documents and the "No Further Action" decision. This OU 3-14 Additional Soil Sites Summary Report presents the archived information and regulatory actions that have been taken with regard to the soil Sites CPP-61, CPP-81, and CPP-82. Evaluation of this information supports previous determinations of "No Further Action" for CPP-61, CPP-81, and CPP-82.

This report covers the historical information for soil Sites CPP-61, CPP-81, and CPP-82. This information supplements the Track 1 reports that were prepared for these soil sites. Section 1 is an introduction summarizing how the soil sites became part of OU 3-14 and the need for this report to evaluate all known information on the sites. Section 2 addresses soil Site CPP-61, Section 3 addresses soil Site CPP-81, and Section 4 addresses soil Site CPP-81. Section 5 is the reference section, and Appendices A through E provide additional information to support the body of the report. Appendix A is the various letters and documents that pertain to CPP-61. Photographs pertaining to CPP-61 are in Appendix B. The daily construction log excerpts that pertain to CPP-61 are in Appendix C. Appendix D is the calcine data and calculations prepared for CPP-81 on the calcine amount removed. Appendix E contains the white papers prepared by Science Applications International Corporation (SAIC) on the three soil sites.




Figure 1-1. Environmentally controlled areas CPP-61, CPP-81, and CPP-82 within INTEC (2001 site plan).